

LD-V8000 Version Upgrade

Contents

1. Version Upgrade Description

Hardware & Software

2. Now to Identify an Upgraded LD-V8000

3. LD-V8000 EPROM Upgrade Kit

1. LD-V8000 Version Upgrade

Pioneer New Media Technologies, has implemented a version upgrading the LD-V8000 industrial videodisc player. All LD-V8000 players manufactured after August 1993. Contain the following hardware and software enhancements and modifications.

Software:

1. Laser Barcode
2. Level II Video Memory Control
3. Audio Sync Lock
4. Added Operational Hour Meter
5. Added Interleaving Playback
6. Improved the following - Won't read dump program by *D command

2. How to Identify and Upgraded LD-V8000

The new version of the players can be identified by, the date of manufacture and entering Test Mode.

3. LD-V8000 EPROM Upgrade Kit

Pioneer New Media Technologies and Pioneer Electronic Service have created an LD-V8000 EPROM Upgrade kit for customers who want to upgrade their existing players. The kit consists of two EPROMs. They are IC-9 DYW-1208 and IC-10 DYW-1244.

The kit maybe ordered from Pioneer Electronic Service by calling:

800-972-4159

Note: Its is strongly recommended that EPROMs be replaced by a Pioneer Authorized Service Technician. If you decide to install upgrade EPROMs yourself, you run the risk of voiding the players warranty. Call 800-872-4159 for your nearest Pioneer Authorized Service Center.