



Pioneer DV-505

Macro Disable mod details

Solder points shown at own risk.

Certain "Firmware" versions restrict the operation of this modification.

Please check with us first to confirm compatibility.

Tel:01708 764 994



Pioneer DV-505 MPEG board caption

[back](#)